

# Interference Search

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L16	5231	(compress\$6 near5 (stress\$6 or strain\$6)).clm.	US-PGPUB; USPAT	OR	ON	2005/11/23 14:35
L17	14	16 and (solder\$6 near5 (bump or ball or electrode)).clm.	US-PGPUB; USPAT	OR	ON	2005/11/23 14:36

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L12	54181	compress\$6 near5 (stress\$6 or strain\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/23 14:16
L13	5632	12 and (pad or bondpad or metallizat\$6)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/23 14:16
L14	498	13 and (solder\$6 near5 (bump or ball or electrode))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/23 14:17
L15	337	14 and (@ad<"20010921" or @rlad<"20010921")	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/23 14:18